

Autoscope IntelliSight

v4.3.1 Release Summary
June 2024



Overview

We have added authentication to the web server and bug fix to the Autoscope IntelliSight version 4.3.1 minor release.

New Features

Web Server Authentication

We've added the ability to add a username and password to the web server. This addition also changed all web server communication from HTTP to HTTPS, and the default port number changed from 80 to 443. By default, new devices have web server authentication enabled.

Webserver	
Port	<input type="text" value="443"/>
Authentication	<input type="button" value="Enabled"/>
Username	<input type="text" value="admin"/>
Password	<input type="password" value="*****"/>
Confirm Password	<input type="password" value="*****"/>

Note: If authentication is enabled, you will be prompted for a password when downloading data.

Fixes

We fixed a bug in this release:

- The system could go into failsafe if the defined NTP server is not found.

Documentation

HTML Help is accessible using the F1 function key. You may also access the Help files directly from the Start menu without running the client application. Help files are also available online. Scan the QR code to the right to access the Online Help or by visiting bit.ly/3PB3ztL



The **User Guide** is accessible from the Image Sensing Systems website. This guide has both the Autoscope Hardware Installation Guide and the Supervisor Software User Guide. Scan the QR code to the left to access the User Guide or by visiting bit.ly/4847bgx then refer to **Downloads - Documentation - Autoscope IntelliSight User Guide**.