

# Autoscope IntelliSight

v4.4.1 Release Summary  
April 2025



## Overview

We have added some new features and implemented performance improvements and bug fixes to the Autoscope IntelliSight version 4.4.1 release.

## New Features

### Phase Information Available in the API

We have included phase information in the API. For more information about the available data, please refer to the API documentation.

To enable phase data for a zone, **right-click** on the **zone** and **select** the appropriate **phase number** and, if applicable, the FYA mode. Once you make these selections, phase data will be incorporated into bin statistics moving forward.

**NOTE:** Only valid FYA modes for the selected phase will be available to select.

**NOTE:** The data will be included only if the API is enabled.



## Performance Improvements

We made detection improvements in the following areas:

- We reverted to the previous model in version 4.3.1 to address some detection issues that were reported, but the other performance improvements in version 4.4.0 were not removed.

## Fixes

We fixed a bug in this release:

- We eliminated the seven-day limit for USB recordings, allowing more videos to be stored on larger drives.

## Documentation

**HTML Help** is accessible using the F1 function key. You may also access the Help files directly from the Start menu without running the client application. Help files are also available online. Scan the QR code to the right to access the Online Help or by visiting [bit.ly/3PB3ztL](https://bit.ly/3PB3ztL)



The **User Guide** is accessible from the Image Sensing Systems website. This guide has both the Autoscope Hardware Installation Guide and the Supervisor Software User Guide. Scan the QR code to the left to access the User Guide or by visiting [bit.ly/4847bgx](https://bit.ly/4847bgx) then refer to **Downloads - Documentation - Autoscope IntelliSight User Guide**.